


**BS**




**BS 1**



**BS 500 - 1000 - 1200**



| Pos | Code  | Description | NOTE | Q. |
|-----|-------|-------------|------|----|
| 1   | BS.01 | BS-1        |      | 1  |
| 2   | BS.02 |             |      | 0  |
| 3   | BS.03 |             |      | 0  |
| 4   | BS.04 |             |      | 0  |
| 5   | BS.05 |             |      | 0  |
| 6   | BS.06 |             |      | 0  |
| 7   | BS.07 |             |      | 0  |
| 8   | BS.08 |             |      | 0  |
| 9   | BS.09 |             |      | 0  |
| 10  | BS.10 |             |      | 0  |
| 11  | BS.11 |             |      | 0  |



| Pos | Code      | Description   | NOTE | Q. |
|-----|-----------|---------------|------|----|
| 1   | BS.02.001 | Main frame    |      | 1  |
| 2   | BS.02.002 | Spear         |      | 1  |
| 3   | BS.02.003 | Small Spear   |      | 1  |
| 4   | BS.02.004 | U bolt        |      | 1  |
| 5   | BS.02.005 | nut           |      | 1  |
| 6   | BS.06     |               |      | 1  |
| 7   | BS.07     |               |      | 1  |
| 8   | BS.08     |               |      | 1  |
| 9   | BS.02.009 | Bolt          |      | 1  |
| 10  | BS.02.010 | Plain Washer  |      | 1  |
| 11  | BS.02.011 | Spring Washer |      | 1  |
| 12  | BS.02.012 | Nut           |      | 1  |